844-724-CARE WWW.GARLAND-GROUP.COM

Service Bulletin

Subject: XP E/G & M E/G Grill UI

To: All Factory Authorized Service (FAS) Agents

Market: AIC

Date: 27th Aug 2021

UI Controller Compatibility Support

Hello All,

Further to the recent communication I sent regarding the obsolescence of the old ME, MG, XPE and XPG controller I wanted to follow up with some additional information to support you to ensure you have and order the correct kit and also understand the impact of compatibility of these changes

Side By side of the old and new controller



Existing HRCB+ controller (Ultratroniks)


New Common Controller (Jabil/ Merco Ultratroniks)

Note. The HRCB+ Ultratroniks UI is physically different in size so cannot be used to replace any Jabil controller

There is likely to be a frequent change in the part numbers over the coming months as we have to make changes in suppliers in order to ensure a supply of the controllers are possible.

On the following page I have added a table to support you with understanding the forward and backwards compatibility of the parts. I have also added 2 rows that will not have a part number yet as they are expected future alterations that are not yet setup but are believed to enter the supply chain in November.

Where possible we are trying to minimise these changes and the product lines impacted as we appreciate that part number changes add a lot of confusion and complication to service and parts department. For this reason, it is essential that we ask you to please ensure this update is shared within your spare parts and technical departments so we can work together to avoid trips in which incompatible controllers are taken



844-724-CARE WWW.GARLAND-GROUP.COM

Compatibility and installation date table

| Controller | Part | Installed from | Last installed | Backward | Forward | MCD/ | Wendys | CFA |
|--------------|---------|-----------------|----------------|------------|------------|------|--------|-----|
| Name | number | Serial Number | Serial number | compatible | Compatible | GM | | |
| Ultratroniks | 4604186 | 1701100100001 | 2103100109999 | Yes | No | Х | | Х |
| HRCB+ | | | | | | | | |
| Jabil 03 | 4606941 | 2104100100001 | 2106100101689 | Yes | Yes | Х | | |
| Jabil 02 | 4607650 | 2106100101690 | Current | Yes | Yes | Х | Х | |
| Merco | TBC | Likely | | Yes | Yes | Х | | |
| Ultratroniks | | November 2021 | | | | | | |
| New | TBC | Likely Jan 2022 | | Yes | Yes | Х | Х | Х |
| Common | | (TBC) | | | | | | |
| Control | | | | | | | | |

Software compatibility and current version.

| Controller Name | Part number | Current software Version | Previous versions | Reset software available | Compatible software with other UI's |
|-----------------------|----------------|--------------------------------|--------------------|--------------------------------|-------------------------------------|
| Ultratroniks HRCB+ | 4604186 | 4.0.5 | 3.0.50, 3.0.55, | Yes | No |
| MCD/GM | | | 4.0.1, 4.0.3 | | |
| Ultratroniks HRCB+ | CK4603097 | 4.4.3 | Older software | Yes | No |
| Chick Fil A | | | must be updated | | |
| Jabil 03 and Jabil 02 | 4606941 & | 1.0.5 | 1.0.3 (should be | No | No |
| controller (McD & | 4607650 | | upgraded to 1.0.5) | | |
| GM) | | | | | |

Please note.

Software from the Jabil controller and the Ultratroniks controllers are not compatible so please ensure you are only trying to load the correct software onto a compatible controller





844-724-CARE WWW.GARLAND-GROUP.COM

Known issues;

Jabil 03

- Software 1.0.3 has issues that can cause the speaker to fail or the controller to reset
 - Solution update to 1.0.5 software (immediate action is to reduce speaker volume to medium until software can be installed)
- System running slow
 - Solution update to 1.0.5
- Controller not booting correctly
 - Solution check the harness adaptor cable to the RJ45 cable as it can be caused by a poor connection

Jabil 02

Early units prior to serial 2107100100855 had been fitted with a short RJ45 cable. Be very cautious when lowering the front panel as it can put tension on the SIB RJ45 socket and cause it to damage the socket. This will require a new SIB. Units after 2107100100856 are fitted with an extension cable to prevent this.

We will continue to communicate and updated information as we move forward to ensure you are best prepared to handle any part changes or challenges, we may find with the controller changes

Thank you all in advance

Brendan Daly Global Service manager



Document Number: CS-08-21-ACI 08/21