

Service Bulletin

Subject: XP E/G & M E/G Grill UI

To: All Factory Authorized Service (FAS) Agents

Market: AIC

Date: 23 Sep 2021

Jabil UI Software update 1.0.3

Hello All,

I wanted to highlight the recent issues we have found in the 1.0.3 Jabil software. This software was only installed on the new ME, MG / XPE, XPG Clamshell grills using the Jabil controller from April 2021 – May 2021

If you find you are installing a unit within this serial number range 2104100100001 – 2105100199999 then I would ask that you update the software to the latest 1.0.5 Jabil revision.

The software version can be found by following the simple steps below

Enter Diagnostics → **Revisions** → **Scroll down until you see**

UI software, it should say either 1.0.3 (old version that needs updating) or 1.0.5 (Latest version no action required)

The software update can be downloaded from <https://clamshell.garland-group.com/>

It is under Production software: Flashdrive_UIv1.0.5_SIBFWv21.622.zip

Known Jabil 1.0.3 issues

Jabil 03

- Software 1.0.3 has issues that can cause the speaker to fail or the controller to reset
 - Solution – update to 1.0.5 software (immediate action is to reduce speaker volume to medium until software can be installed)
- System running slow
 - Solution – update to 1.0.5
- Controller not booting correctly
 - Solution – check the harness adaptor cable to the RJ45 cable as it can be caused by a poor connection

Thank you all in advance

Brendan Daly
Global Service manager